
Diagram of the LandMark Injection Foam Marker TA components for systems built after January 2014




PART #	DESCRIPTION
CL0140	CLAMP, FOR 1/4"REINFORCED
EL8160	WP DISCONNECT WIRE LEAD
FM0102	LIQUID IN-LINE CLEANABLE FILTERS 1/4" BARB
FM1206	GREY FIBERGLASS ENCLOSURE BOX
FM3022	2-WAY Smucker Solenoid Valve (air input)
FM3033	3-WAY Smucker Solenoid Valve
FM3300	REGULATOR ASSEMBLY WITH HOSE BARBS
FM6319	PRIMING VALVE
HE02SA	1/4" JG TUBE X 1/4" ELBOW BARB
HT5165	1/4" JG TUBE X 1/4" STRAIGHT BARB
LM1011	PUMP, LM SHUR FLO ASSY
LM1414	LIQUID ANTI SIPHON CHECK VALVE
LM1818	VALVE,NEEDLE,BRS 1/8X1/8
LM1825	1/2 # CHECK VALVE1/8" MPT X 1/4" HB
VL0001	TUBING, REINFORCED 1/4"



FM3300-LM

FM3300

(use this number to include a stainless bracket not shown)



FM6319

FM0102